NOTICE TO MARINERS

NTM: 02/2026 **ISSUED DATE:** 07th January 2026

Northern Gulf: Kuwait – Buoys Permanently Altered in Characteristics.

BA Charts: 2884, 3773, 1223.

Two buoys have been permanently altered in characteristics with same position as below:

From yellow NP -02 to green NP-A with flash code Fl.G.5s and range of 2 N.M at position 29-07.704N, 048-08.416E.

From yellow NP -01 to red NP-B with flash code Fl.R.5s and range of 2 N.M at position 29-07.695N, 048-08.494E.

Mariners requested to navigate with caution and update their BA Charts.

Issuer: MENAS Maritime Operations Centre, Bahrain
Megulite

Mariners are requested to inform the Middle East Navigation Aids Service, P. O. Box 66, Manama, Bahrain immediately on the discovery of new dangers, or suspected dangers to navigation and changes or defects in aids to navigation noticed in Sub-Navarea IX - Gulf and its Approaches.

MENAS is an ISO 9001:2015 Certified Service

All MENAS service users are requested to pass on valid navigational hazard information to the MENAS MARITIME OPERATIONS CENTRE in Bahrain using communications methods:
Tel: +973 17828541 Fax: +973 17727765 Email info@menas.com.bh

MENAS is committed to maritime safety in the region and MENAS support the standards of marine operations recommended by IMCA, the International Marine Contractors Association.
As part of our process of continual improvement of services to the maritime community, we are continually amending / updating our mailing lists. Please reply to this mail address should you require any additional email addresses added to the direct NAVTEX and/or Gulf Notices to Mariners circulation lists.
Please also find latest navigational situation information at menas.org Users are requested to provide suggestions for Service enhancements, navigational hazard feedback and complaints through menas.org

www.menas.org